

## Drive European

30-A Hillwood Ave.  
Falls Church, VA 22046  
PH: 703.536.4500  
FX: 703.536.4789

www.DriveEuropean.com

## INSPECTION REPORT

DATE: 06/13/2018
















Drive European Inspection 02

PAGE: 1

PERFORMED BY:

CUSTOMER: JOHN SMITH  
ADDRESS: 123 ELECTRIC AVE.  
CITY: FALLS CHURCH, VA 22046  
PHONE1:  
PHONE2:

VEHICLE: 2016 AUDI  
LICENSE: V12345678  
VIN: VHGM2456849  
ENGINE: Cyl L5 Disp 2.5  
MILEAGE: 41519 COLOR:

Item #	Description	Checked	Ok	Next Visit	Urgent	Notes
	1. Notes		✓			Mileage:41519
	2. Warning lights				✓	Brake lining
	3. Test for abnormal vibration.		✓			
	4. Brake jab-susp. joint test.		✓			
	5. Test-heater-defrost-ac		✓			
	6. Test wipers+washers+visua		✓			LABOR: PARTS:
	7. Eng. running-noises-pulleys		✓			
	8. Inspect belt		✓			LABOR: PARTS:
	9. Brake fl. moisture-ck history		✓			LABOR: PARTS:
	10. Cooling system test+hoses		✓			LABOR: PARTS:
	11. Bat. test		✓			LABOR: PARTS:
	12. Visual insp. eng. bay-leaks		✓			LABOR: PARTS:
	13. Exterior lights		✓			LABOR: PARTS:
	14. Suspens.test 4 corners		✓			
	15. Tire Measurement- %				✓	LABOR: Replace 2 tires-rear tires are worn to the markers and unevenly. fronts are OK. PARTS:

This inspection is not a comprehensive list of all items that could impact drivability and safety but rather key items we consider important regarding your operation of the vehicle. Because many items can fail without warning and may not show any indication of potential failure during an inspection, we are in no way guaranteeing that our inspection and subsequent repairs will prevent drivability or safety issues. However, we strongly recommend that you consider for repair any items marked Next Visit or Urgent.

## Drive European

30-A Hillwood Ave.  
Falls Church, VA 22046

PH: 703.536.4500

FX: 703.536.4789

www.DriveEuropean.com

## INSPECTION REPORT

DATE: 06/13/2018

Drive European Inspection 02

PAGE: 2

PERFORMED BY:

CUSTOMER: JOHN SMITH  
ADDRESS: 123 ELECTRIC AVE.  
CITY: FALLS CHURCH, VA 22046  
PHONE1:  
PHONE2:

VEHICLE: 2016 AUDI  
LICENSE: V12345678  
VIN: VHGM2456849  
ENGINE: Cyl L5 Disp 2.5  
MILEAGE: 41519 COLOR:

### Item # Description Checked Ok Next Visit Urgent Notes



#### 15. Tire Measurement- % (continued)



#### 16. Front brake pads-mm



LABOR: Replace front pads and rotors-Worn  
PARTS:Pads+Rotors+Sensor

This inspection is not a comprehensive list of all items that could impact drivability and safety but rather key items we consider important regarding your operation of the vehicle. Because many items can fail without warning and may not show any indication of potential failure during an inspection, we are in no way guaranteeing that our inspection and subsequent repairs will prevent drivability or safety issues. However, we strongly recommend that you consider for repair any items marked Next Visit or Urgent.

## Drive European

30-A Hillwood Ave.  
Falls Church, VA 22046

PH: 703.536.4500

FX: 703.536.4789

www.DriveEuropean.com

## INSPECTION REPORT 000020603

DATE: 06/13/2018

Drive European Inspection 02

PAGE: 3

PERFORMED BY:

CUSTOMER: JOHN SMITH  
ADDRESS: 123 ELECTRIC AVE.  
CITY: FALLS CHURCH, VA 22046  
PHONE1:  
PHONE2:

VEHICLE: 2016 AUDI  
LICENSE: V12345678  
VIN: VHGM2456849  
ENGINE: Cyl L5 Disp 2.5  
MILEAGE: 41519 COLOR:

### Item # Description Checked Ok Next Visit Urgent Notes



#### 16. Front brake pads-mm (continued)



#### 17. Rear brake pads-mm



LABOR:  
PARTS:



#### 18. Shock absorbers+mounts



LABOR:  
PARTS:



#### 19. Fluid leaks



LABOR:  
PARTS:



#### 20. R.F. Suspension



LABOR:  
PARTS:



#### 21. R.F. Steering+rack boot+



LABOR:  
PARTS:



#### 22. L.F. Suspension



LABOR:  
PARTS:

This inspection is not a comprehensive list of all items that could impact drivability and safety but rather key items we consider important regarding your operation of the vehicle. Because many items can fail without warning and may not show any indication of potential failure during an inspection, we are in no way guaranteeing that our inspection and subsequent repairs will prevent drivability or safety issues. However, we strongly recommend that you consider for repair any items marked Next Visit or Urgent.

**Drive European**30-A Hillwood Ave.  
Falls Church, VA 22046

PH: 703.536.4500

FX: 703.536.4789

www.DriveEuropean.com

**INSPECTION REPORT** 000020603

DATE: 06/13/2018

Drive European Inspection 02

PAGE: 4

PERFORMED BY:

CUSTOMER: JOHN SMITH  
ADDRESS: 123 ELECTRIC AVE.  
CITY: FALLS CHURCH, VA 22046  
PHONE1:  
PHONE2:VEHICLE: 2016 AUDI  
LICENSE: V12345678  
VIN: VHGM2456849  
ENGINE: Cyl L5 Disp 2.5  
MILEAGE: 41519 COLOR:





















Item #	Description	Checked	Ok	Next Visit	Urgent	Notes
	23. L.F. Steering+rack boot					LABOR: PARTS:
	24. Front Axles/boots if appl.					LABOR: PARTS:
	25. Eng.+trans+frame mouts					LABOR: PARTS:
	26. Driveshaft+disc+joints					LABOR: PARTS:
	27. Exhaust and mounts+					LABOR: PARTS:
	28. L.R. Suspension					LABOR: PARTS:
	29. R.R. Suspension					LABOR: PARTS:
	30. Diff+subframe mounts					LABOR: PARTS:
	31. Diagnostic test needed?					LABOR: PARTS:
	32. Alignment					Due to uneven tire wear.
	33. Rotation+balancing at 10K					LABOR: PARTS:
	34. Timing belt 7yrs. or mileag					LABOR: PARTS:
	35. ATF Manufacturer or 100k					LABOR: PARTS:
	36. Spark Plugs due?					LABOR: PARTS:
	37. What services are due?					LABOR: PARTS:

This inspection is not a comprehensive list of all items that could impact drivability and safety but rather key items we consider important regarding your operation of the vehicle. Because many items can fail without warning and may not show any indication of potential failure during an inspection, we are in no way guaranteeing that our inspection and subsequent repairs will prevent drivability or safety issues. However, we strongly recommend that you consider for repair any items marked Next Visit or Urgent.

**Drive European**30-A Hillwood Ave.  
Falls Church, VA 22046**PH: 703.536.4500****FX: 703.536.4789**

www.DriveEuropean.com

**INSPECTION REPORT 000020603****DATE:** 06/13/2018**Drive European Inspection 02****PAGE:** 5**PERFORMED BY:**CUSTOMER: JOHN SMITH  
ADDRESS: 123 ELECTRIC AVE.  
CITY: FALLS CHURCH, VA 22046  
PHONE1:  
PHONE2:VEHICLE: 2016 AUDI  
LICENSE: V12345678  
VIN: VHGM2456849  
ENGINE: Cyl L5 Disp 2.5  
MILEAGE: 41519 COLOR:

Item #	Description	Checked Ok	Next Visit	Urgent	Notes
	38. State Inspection				
	39. Other tasks				LABOR: PARTS:
	40. Other tasks				LABOR: PARTS:
	41. Other tasks				LABOR: PARTS:
	42. Other task				LABOR: PARTS:

This inspection is not a comprehensive list of all items that could impact drivability and safety but rather key items we consider important regarding your operation of the vehicle. Because many items can fail without warning and may not show any indication of potential failure during an inspection, we are in no way guaranteeing that our inspection and subsequent repairs will prevent drivability or safety issues. However, we strongly recommend that you consider for repair any items marked Next Visit or Urgent.